

## VEHICLE INSPECTION REPORT

**MD23UHX**

### Peugeot Expert 1000 1.5 BlueHDi 100PS Professional

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Present

#### Details

Reg. date 02/06/2023

Year 2023

Mileage 31,468 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN VF3VBYHRMP7820858

Body Style Panel Van

MOT Due 01/06/2026

CAP Clean £11,700.00

CAP Average £11,000.00

CAP Below £9,700.00

Gearbox MANUAL

Gears 6

AD-BLUE, E/ MIRRORS, TWIN SIDE LOAD DOOR

#### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Auxiliary input socket
- Drivers airbag
- Cruise control
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Qtr Panel nsr  
Dented  
With Paint Damage



4: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm



5: Bumper Rear  
Scratched  
Over 100mm Thru Paint



6: Door osf  
Dented  
With Paint Damage

### Interior

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	OK	<b>Odour</b>	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		