

VEHICLE INSPECTION REPORT

R25NNO

Renault T-HIGH 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Livingston	Colour	BLACK	Axle Combi	6x2
Reg. date	21/03/2024	VIN	VF610M362PD001951	Steering Combi	Rear-Lift Steer
Year	2024	Body Style	Curtainside	Rear Suspension	Air
Mileage	105,376 Km Not Warranted	MOT Due	30/04/2027	Rear Doors	Barn
Fuel Type	Diesel	Cab Type	SLEEPER CAB	Tail Lift	Tuckaway
GVW	26000kg	Gearbox	AUTOMATIC		

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Air conditioning
- Cloth seat trim
- Cruise control
- Front electric windows
- Park assist camera
- Drivers airbag
- Radio/CD
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
UpTo 25mm Not Thru Paint



3: Door Moulding osf
 Scratched (Painted)
 Over 25mm Thru Paint

4: Door Moulding nsf
 Scratched (Painted)
 Over 25mm Thru Paint



5: Tailgate
 Dented
 With Paint Damage

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	

Windows

OK

Radio

OK

Steering

OK