

VEHICLE INSPECTION REPORT

RO23LWT

Peugeot Expert 1000 1.5 BlueHDi 100PS Professional

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 28/04/2023

VIN VF3VBYHRMN7079462

CAP Below £9,750.00

Year 2023

Body Style Panel Van L1

Gearbox MANUAL

Mileage 29,992 Miles Not Warranted

MOT Due 27/04/2026

Gears 6

Fuel Type Diesel

CAP Clean £11,750.00

Colour BLACK

CAP Average £11,100.00

WARNING LIGHT ON DASH AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



3: Door osr
Scratched
Over 25mm Thru Paint



4: Qtr Panel osr
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint




6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Door osf
Scratched
Over 25mm Thru Paint



9: Seat Base Cover osf
Soiled
Heavy



10: Dash Warning Lights
Displayed
No Action

Interior

| | | | | | |
|-----------------------|--|------|-------------------------------------|--|-------|
| Carpet Condition | | OK | Upholstery Condition | | OK |
| Seat Condition | | Poor | Odour | | - |
| Engine Runs | | OK | No Excessive Smoking | | OK |
| EML light illuminated | | OK | DPF light illuminated | | OK |
| ABS light illuminated | | OK | Service indicator light illuminated | | Fault |