

VEHICLE INSPECTION REPORT

HX73YPH

Mercedes-Benz Atego 816

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	19/10/2023	Colour	WHITE	Cab Type	DAY CAB
Year	2023	VIN	W1T96700120671096	Gearbox	AUTOMATIC
Mileage	18,073 Km Warranted	Body Style	Flatbed & Crane	Axle Combi	4x2
Fuel Type	Diesel	Service history	Yes	Rear Suspension	Steel
GVW	7490kg	MOT Due	31/10/2026		

PALFINGER PK 5.501 SLD5 REMOTE CRANE (YEAR 2023), WEIGH SYSTEM

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Digital radio
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Auxiliary input socket
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Panel Front
Cracked
Replace




2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Bumper Front
 Scratched
 Over 100mm Thru Paint

4: Wing osf
 Scratched
 Over 25mm Thru Paint



5: Seat Base Cover osf
 Soiled
 Heavy

6: Seat Back Cover osf
 Soiled
 Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		