

VEHICLE INSPECTION REPORT

YK23DCB

Suzuki S-Cross 1.4 BOOSTERJET 48V MOTION

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Buyer To Apply

Details

Reg. date	16/08/2023	Colour	BLUE	CAP Below	£7,825.00
Year	2023	VIN	TSMJYAD2S00A75149	Gearbox	MANUAL
Mileage	44,540 Miles Not Warranted	Body Style	Hatchback	Gears	6
Fuel Type	Hybrid Electric	CAP Clean	£10,150.00	Doors	5
GVW	1685kg	CAP Average	£9,000.00		

INFOTAINMENT SYSTEM INOP KEYLESS IGNITION

Tyres

NSF

NSR

OSF


OSR


Spare


Features

- Front parking sensor
- Body coloured bumpers
- Front electric windows
- Heated front seat
- Electric door mirrors
- Rear electric windows
- Park assist camera
- Air conditioning
- Alloy wheels
- Rear parking sensor
- Climate control


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint

2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
UpTo 10mm

4: Wing Front Arch Extension ns
Scuffed (Unpainted)
UpTo 100mm



5: Wheel nsf
Scratched
Up To 50mm

6: Door nsr
Dented
With Paint Damage



7: Door nsr
Scratched
Over 25mm Thru Paint

8: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK