

# VEHICLE INSPECTION REPORT

**DA69DMF**

## Daf CF 340

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date	01/01/2020	VIN	XLRASM4100G283128	Axle Combi	6x2
Year	2020	Body Style	Box Van	Rear Suspension	Air
Mileage	547,593 Km Warranted	MOT Due	31/03/2026	Rear Doors	Roller
Fuel Type	Diesel	Cab Type	SPACE CAB	Tail Lift	Column
Colour	WHITE	Gearbox	AUTOMATIC		

\*WARNING LIGHT ON DASH\* REAR LIFT


### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


## Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


## Photos








## Condition Check



## Damage Photos



1: Seat Base Cover nsf  
Soiled  
Heavy



2: Dash Warning Lights  
Displayed  
No Action





3:

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-

EML light illuminated	Fault
ABS light illuminated	OK