

VEHICLE INSPECTION REPORT

FL69XAZ

Vauxhall Vivaro 2900 1.5D 100PS EDITION

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 29/11/2019

Year 2019

Mileage 82,114 Miles
Warranted

Fuel Type DIESEL

GVW 2830kg

Colour WHITE

VIN VXEVBYHRKL7005645

Body Style Panel Van L1

MOT Due 18/05/2027

CAP Clean £5,650.00

CAP Average £4,875.00

CAP Below £3,800.00

Gearbox MANUAL

Gears 6

COLLECTED AS NON-RUNNER, WARNING LIGHTS ON DASH AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS, RACKING IN REAR, DEADLOCKS (NO KEYS)

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos








Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint

2: Bonnet
Chipped
Multiple Chips



3: Panel Front
Scratched
Over 25mm Thru Paint

4: Door nsf
Dented
Over 30mm



5: Sill ns
Dented
Over 30mm

6: Door osf
Dented
Over 30mm



7: Wing osf
Scratched
Over 25mm Thru Paint

8: Seat Base Cover nsf
Soiled
Heavy



9: Seat Back Cover osf
Soiled
Heavy

10: Dash Warning Lights
Displayed
No Action



11: Door Mirror Assy osf
Broken
Replace

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK		