

VEHICLE INSPECTION REPORT

AY71SFU

Mercedes-Benz Actros 2545

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	17/01/2022	Colour	WHITE	Gearbox	AUTOMATIC
Year	2022	VIN	W1T96342320550446	Axle Combi	6x2
Mileage	622,380 Km Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Fuel Type	DIESEL	MOT Due	31/12/2026	Rear Suspension	Air
GVM	44000kg	Cab Type	STREAMSPACE CAB (2.5M, FLAT FLOOR)		

FLAT BATTERY, WARNING LIGHT ON DASH, MIRROR CAMERAS


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Air conditioning
- Cloth seat trim
- Cruise control
- Front electric windows
- Digital radio
- Drivers airbag
- Electric sunroof
- Central locking

Photos





Condition Check



Damage Photos



1: Wing nsf
Scratched
Over 25mm Thru Paint

2: Door nsf
Scratched
Over 25mm Not Thru Paint




3: Qtr Panel osr
Cracked
Replace



4: Fuel Flap
Missing
Replace



5: Wing Front Arch Extension ns
Missing
Replace



6: Boot Lid
Missing
Replace




7: Qtr Panel osr
Cracked
Replace



8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Door osf
Scratched
Over 25mm Thru Paint



10: Door osf
Dented
With Paint Damage



11: Moulding osf Wing
Missing
Replace



12: Centre Console Front
Holed
Over 3mm



13: Dash Warning Lights
Displayed
No Action

14: Fascia Trim
Damaged
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		