

VEHICLE INSPECTION REPORT

YG17HWJ

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	06/06/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	XLRAEL3700L459460	Gearbox	MANUAL
Mileage	174,607 Km Warranted	Body Style	Dropside & Crane	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	28/02/2026	Rear Suspension	Steel

HMF 1420K-RC REMOTE CRANE (YEAR 2006), BEEN ON FULL R&M CONTRACT FROM NEW

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Park assist camera
- Digital radio
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Panel Front
Cracked
Replace



4: Door osf
Dented
With Paint Damage



5: Door osf
Dented
With Paint Damage



6: Door osf
Scratched
Over 25mm Thru Paint



7: Door Pad osf
Soiled
Heavy



8: Door Pad nsf
Soiled
Heavy



9: Seat Base Cover nsf
Soiled
Heavy



10: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition		OK	Upholstery Condition		Poor
Seat Condition		OK	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			