

VEHICLE INSPECTION REPORT

LD23EFG

Citroen Relay 35 2.2 BLUEHDI 140PS ENTERPRISE

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	31/08/2023	Colour	WHITE	CAP Average	£9,225.00
Year	2023	VIN	VF7YCBPFCPG030262	CAP Below	£7,925.00
Mileage	62,008 Miles Not Warranted	Body Style	Panel Van L3	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	30/08/2026	Gears	6
GVW	3500kg	CAP Clean	£9,975.00	Axle Combi	4x2

WARNING LIGHT ON DASH, ENGINE KNOCKS HEAVILY, 2 X FLAT/DAMAGED TYRES, UNABLE TO UNLOCK SIDE & REAR DOORS, AD BLUE, SIDE LOAD DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Rear parking sensor
- Digital radio
- Air conditioning
- Drivers airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Qtr Panel nsr
Dented
Over 30mm



2: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



3: Wheel nsr
Damaged
Replace

4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



5: Handle Outer nsr
Scratched (Painted)
UpTo 25mm Thru Paint

6: Door nsr
Scratched
Over 25mm Thru Paint



7: Door osr
Scratched
Over 25mm Thru Paint

8: Wheel nsf
Damaged
Replace



9: Door Mirror Assy osf
Broken
Replace

10: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		-	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	Fault		Gearbox 1st and Reverse Test		OK
Brakes	OK		Gearbox Static Gear Selection (engine running)		OK
Parking Brake	OK		No Excessive Smoking		OK
EML light illuminated	OK		DPF light illuminated		OK
Airbag light illuminated	OK				
ABS light illuminated	OK				