

VEHICLE INSPECTION REPORT

VCL514S

VOLVO F88

Inspection

Vehicle

VAT	Margin
V5	To Follow

Details

Reg. date	01/08/1977	Colour	WHITE/BROWN	Gearbox	Manual
Year	1977	VIN	56915	Axle Combi	4x2
Mileage	232,025 Km Not Warranted	Body Style	Tractor Unit		
Fuel Type	DIESEL	Cab Type	SLEEPER CAB		

Tyres

NSF

NSR

OSF

OSR

Spare

Photos







