

VEHICLE INSPECTION REPORT

RAE810S

VOLVO F86

Inspection

Vehicle

VAT	Margin
V5	To Follow

Details

Reg. date	13/04/1977	Colour	MAROON/SILVER	Gearbox	Manual
Year	1977	VIN	33873	Axle Combi	4x2
Mileage	69,500 Km Not Warranted	Body Style	Tractor Unit		
Fuel Type	DIESEL	Cab Type	DAY CAB		

Tyres

NSF
NSR
OSF
OSR
Spare

Photos







