

VEHICLE INSPECTION REPORT

WR65XFB

Man TGM 18.250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 22/12/2015

GVW 18000kg

Cab Type DAY CAB

Year 2015

Colour YELLOW

Gearbox MANUAL

Mileage 48,649 Km Not Warranted

VIN WMAN38ZZ1GY336980

Axle Combi 4x4

Fuel Type DIESEL

Body Style Gritter

Rear Suspension Steel

WARNING LIGHTS ON DASH ECON WZCMHJ46 BODY, PLOUGH, HUB REDUCTION


Tyres








NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4



Features

- Cruise control
- Cloth seat trim
- Radio/CD
- Front electric windows
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Hole
UpTo 10mm



2: Bumper Front
Dented
With Paint Damage



3: Door Mirror Assy nsf
Broken
Replace

4: Wing nsf
Scratched
Over 25mm Thru Paint




5: Wing osf
Scratched
Over 25mm Thru Paint

6: Door Mirror Assy osf
Broken
Replace



7: Carpets Front
Holed
Over 3mm

8: Dash Warning Lights
Displayed
No Action



Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault