

VEHICLE INSPECTION REPORT

FD71BZY

Vauxhall Vivaro 3100 2.0 145PS Dynamic

Non Runner
Inspection

Serious Damage?	No	Vehicle	
		VAT	Plus VAT
		V5	Buyer To Apply

Details

Reg. date	31/12/2021	VIN	VXEVEHTMM7853169	Cab Type	DAY CAB
Year	2021	Body Style	Panel Van L1	Gearbox	MANUAL
Mileage	68,624 Miles Warranted	MOT Due	30/12/2026	Gears	6
Fuel Type	DIESEL	CAP Clean	£8,800.00	Doors	2
GVW	3100kg	CAP Average	£7,850.00	Steering Combi	Standard Axle
Colour	WHITE	CAP Below	£6,425.00	Rear Suspension	Steel

* NON RUNNER DOESNT START OR DRIVE - ENGINE PARTS IN CAB *

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Bluetooth connection
- Drivers airbag
- Radio/CD
- Central locking
- Air conditioning
- Partial leather seat trim
- Front electric windows

Photos





Condition Check



Damage Photos



1: Sill os
Scratched
UpTo 25mm Thru Paint

2: Bonnet
Dented
Over 30mm



3: Door osr
Dented
With Paint Damage

4: Door nsr
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Engine Runs **Fault**