

VEHICLE INSPECTION REPORT

T75544

NIFTYLIFT HR17 NGET75544

Non Runner
Inspection

Vehicle	
VAT	Plus VAT
V5	Buyer To Apply

Details

Reg. date	01/01/2011	Fuel Type		Body Style	Access Platform
Year	2011	Colour	GREEN		
Mileage	Not Showing	VIN			


NON-RUNNER - REQUIRES NEW BATTERY

Tyres

NSF
NSR
OSF
OSR
Spare

Photos





Engine Runs	Fault	Gearbox 1st and Reverse Test	Fault
Brakes	Fault	Clutch Slip Test from Static	Fault
Turbo Boosting	Fault	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	Fault	No Excessive Smoking	Fault
EML light illuminated	Fault	Oil warning light illuminated	Fault
Airbag light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	Fault	Service indicator light illuminated	Fault
Windows	Fault	Radio	Fault
		Steering	Fault