

VEHICLE INSPECTION REPORT

GF69TCV

Daf XF 530

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 08/11/2019

Year 2019

Mileage 516,300 Km Not Warranted

Fuel Type DIESEL

GVW 44000kg

Colour WHITE

VIN XLRTGH4300G290565

Body Style Tractor Unit

MOT Due 31/03/2027

CAP Clean £11,250.00

CAP Average £10,600.00

CAP Below £9,275.00

Cab Type SUPER SPACE CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift Steer

Rear Suspension Air

WARNING LIGHT ON DASH FRIDGE, MICROWAVE, SLIDING 5TH WHEEL

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Bumper Front
Chipped
Multiple Chips



3: Bonnet
Chipped
1 To 5

4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint

6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel osr
Cracked
Replace

8: Door osf
Chipped
Edge Chip



9: Wing Front Arch Extension os
 Scratched (Painted)
 Over 25mm Not Thru Paint

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	