

VEHICLE INSPECTION REPORT

UAL863R

VOLVO F89

Accident Damage Inspection Imported

Vehicle	
VAT	Margin
V5	To Follow

Details

Reg. date	01/03/2023	Colour	CREAM	Gearbox	Manual
Year	1977	VIN	16637	Axle Combi	4x2
Mileage	145,396 Km Not Warranted	Body Style	Tractor Unit		
Fuel Type	DIESEL	Cab Type	SLEEPER CAB		

Vehicle Recorded As DVLA SCRAPPED MARKER On Condition Alert Registr., LEFT HAND DRIVE

Tyres

NSF
NSR
OSF
OSR
Spare

Photos





