

VEHICLE INSPECTION REPORT

KRB141N

VOLVO F89

Imported
Inspection

Vehicle	
VAT	Margin
V5	To Follow

Details

Reg. date	01/03/2023	Colour	CREAM	Gearbox	Manual
Year	1975	VIN	04439	Axle Combi	4x2
Mileage	740,720 Km Not Warranted	Body Style	Chassis Cab		
Fuel Type	DIESEL	Cab Type	SLEEPER CAB		

LEFT HAND DRIVE

Tyres

NSF
NSR
OSF
OSR
Spare

Photos





