

VEHICLE INSPECTION REPORT

PN65PZL

Daf XF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 22/10/2015

Colour WHITE

Axle Combi 6x2

Year 2015

VIN XLRASH4100G067338

Rear Suspension Air

Mileage 331,265 Km Warranted

Body Style Flatbed & Crane

Fuel Type Diesel

Gearbox Automatic

REAR LIFT, PALFINGER EPSILON TIPPER 2 EASY FOLD (2 EXT) REMOTE CRANE (2015), DRAWBAR COUPLING

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Cruise control
- Navigation system
- Radio/CD
- Air conditioning
- Front electric windows
- Drivers airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Door Moulding osf
Scuffed (Unpainted)
Over 100mm




3: Sill os
Rusted
Over 5mm




4: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint



5: Bonnet
Chipped
Over 5mm



6: Bumper Front
Scratched
25 to 100mm Thru Paint



7: Front TowEye Cvr
Missing
Replace



8: Bumper Front
Scratched
25 to 100mm Thru Paint



9: Badgedecal Front
Missing
Replace



10: Front TowEye Cvr
Missing
Replace



11: Wing osf
Scratched
Over 25mm Thru Paint



12: Door osf
Dented
Over 30mm



13: Qtr Panel osr
Rusted
Over 5mm



14: Qtr Panel osr
Rusted
Over 5mm



15: Tailgate
Rusted



16: Qtr Panel nsr
Rusted
Over 5mm



17: Qtr Panel nsr
Dented
Over 30mm



18: Door nsf
Dented
Over 2 UpTo 10mm



19: Wing nsf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		