

VEHICLE INSPECTION REPORT

NV21UJK

Peugeot Partner 1000 1.5 BlueHDi 100 Professional Van

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 02/07/2021

Year 2021

Mileage 33,330 Miles Not Warranted

Fuel Type DIESEL

GVW 2370kg

Colour WHITE

VIN VR3EFYHYCMJ700498

Body Style Panel Van L1

MOT Due Expired

CAP Clean £7,950.00

CAP Average £7,100.00

CAP Below £5,825.00

Gearbox MANUAL

Gears 5

Axle Combi 4x2

OUTSTANDING RECALL, AD BLUE, SIDE LOAD DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Rear parking sensor
- Air conditioning
- Front electric windows

Photos






Condition Check




Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Chipped
1 To 5



3: Door nsf
Chipped
1 To 5

4: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Wing osf
Chipped
Multiple Chips

8: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
Airbag light illuminated		OK			
ABS light illuminated		OK			