

VEHICLE INSPECTION REPORT

HS21LCO

Ford Transit Custom 300 2.0 EcoBlue 130PS LIMITED

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 31/05/2021

Year 2021

Mileage 42,559 Miles Not Warranted

Fuel Type DIESEL

GVW 3000kg

Colour SILVER

VIN WF0YXXTTGYMP68451

Body Style Crew Van L1

MOT Due Expired

Gearbox MANUAL

Gears 6

Rear Suspension Steel

Rear Doors Barn

NSR ALLOY REMOVED AND IN BACK OF VAN

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Bluetooth connection
- Air conditioning
- Central locking
- Cruise control
- Front electric windows
- Leather seat trim
- Front parking sensor
- Drivers airbag
- Rear parking sensor
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Bonnet
Dented
With Paint Damage



3: Bumper Front
Hole
Over 25mm

4: Door osf
Dented
With Paint Damage



5: Tailgate
Dented
With Paint Damage

6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Wheel nsr
Damaged
Replace

8: Door nsf
Dented
With Paint Damage



9: Sill Panel Trim ns
Broken
Replace

10: Wing nsf
Dented
With Paint Damage



11: Roof
Rusted
Over 5mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK

Windows	OK	Radio	OK
		Steering	OK