

VEHICLE INSPECTION REPORT

PE190DC

MULTIHOG MULTEVO MH75

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	15/03/2019	Fuel Type	DIESEL	Body Style	Snow Plough
Year	2019	Colour	YELLOW	Gearbox	HYDROSTATIC
Mileage	268 Hours Not Warranted	VIN	UN9H928Y9KD015336		

SNOWBLOWER 3900 ATTACHMENT

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



