

VEHICLE INSPECTION REPORT

FN19JDJ

Scania S 500

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 27/03/2019

Year 2019

Mileage 828,984 Km Not Warranted

Fuel Type DIESEL

GVW 44000kg

Colour WHITE

VIN YS2S6X20005540468

Body Style Tractor Unit

MOT Due 31/03/2027

Cab Type HIGHLINE CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

WARNING LIGHTS ON DASH TWIN FUEL TANKS, PREMIUM INFOTAINMENT SYSTEM, FRIDGE, MICROWAVE

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3


OSO4



Features

- Bluetooth connection
- Digital radio
- Front electric windows
- Cruise control
- USB/iPod interface
- Central locking
- Front parking sensor
- Manual sunroof
- Cloth seat trim
- Auxiliary input socket
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Front TowEye Cvr
Missing
Replace



3: Screen Front
Chipped
Over 10mm

4: Wing nsf
Chipped
Multiple Chips



5: Door Mirror Assy nsf
Broken
Replace

6: Door nsf
Dented
With Paint Damage



7: Door nsf
Scratched
Over 25mm Thru Paint

8: Parking Sensor Front
Broken
Replace



9: Wing Front Arch Extension ns
Broken
Replace

10: Fuel Flap
Missing
Replace



11: Door osf
Chipped
Multiple Chips

12: Bumper Front
Scratched
Over 100mm Thru Paint



13: Wing osf
Dented
With Paint Damage

14: Bonnet
Hole
Over 10mm



15: Bonnet
Poor Previous Repair
Paint Flake

16: Fascia Trim
Damaged
Replace



17: Centre Console Front
Holed
Over 3mm

18: Dash Warning Lights
Displayed
No Action



19: Fascia Trim
Missing
Replace

20: Fascia Trim
Damaged
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		