

VEHICLE INSPECTION REPORT

BV72JKN

Renault Master 35 L3H1

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 16/09/2022

Year 2022

Mileage 98,003 Miles Not Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN VF6VG000169283619

Body Style Curtainside

MOT Due 04/08/2026

Gearbox MANUAL

Gears 6

Tail Lift Column

*COLLECTED AS NON RUNNER- IN LIMP MODE, WARNING LIGHTS ON DASH *E/MIRRORS, AD-BLUE

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Bluetooth connection
- Air conditioning
- Central locking
- Cruise control
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint

2: Door Mirror Assy nsf
Broken
Replace



3: Door osf
Dented
With Paint Damage

4: Seat Base Cover osf
Torn
Over 3mm



5: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	Fault