

VEHICLE INSPECTION REPORT

BV22GBZ

Renault Master 35 2.3

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 01/04/2022

Year 2022

Mileage 83,631 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN VF6VG000968731711

Body Style Curtainside LWB

MOT Due Expired

Gearbox MANUAL

Gears 6

Tail Lift Column

*COLLECTED AS NON-RUNNER, LIMP MODE**WARNING LIGHTS ON DASH* AD-BLUE, E/ MIRRORS, NEW KEEPER SLIP ONLY

Tyres

NSF

NSR

OSF

OSR




Spare

Features


- Bluetooth connection
- Air conditioning
- Central locking
- Cruise control
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

4: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



5: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

6: Seat Base Cover osf
Burn
Over 3mm



7: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	Fault