

VEHICLE INSPECTION REPORT

DG21FBD

Daf CF 480

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	44000kg	Cab Type	SUPER SPACE CAB
Reg. date	15/04/2021	Colour	WHITE	Gearbox	AUTOMATIC
Year	2021	VIN	XLRTGM4300G350524	Axle Combi	6x2
Mileage	529,058 Km Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift Steer
Fuel Type	DIESEL	MOT Due	30/04/2027	Rear Suspension	Air

SLIDING 5TH WHEEL

Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Digital radio
- Cloth seat trim
- Cruise control
- Air conditioning
- Navigation system
- Front electric windows
- Park assist camera
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



3: Door nsf
Dented
Over 30mm



4: Door nsf
Dented
With Paint Damage



5: Door osf
Dented
Over 30mm



6: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



7: Screen Front
Chipped
Over 10mm



Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		