

VEHICLE INSPECTION REPORT

RO53MDN

Ford Transit Custom 2.0 EcoBlue 130PS 280 Limited

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

Details

Reg. date	20/03/2019	Colour	RED	CAP Average	£6,075.00
Year	2019	VIN	WF0YXXTTGYKC35219	CAP Below	£4,725.00
Mileage	127,051 Miles Not Warranted	Body Style	Motorhome	Gearbox	AUTOMATIC
Fuel Type	DIESEL	MOT Due	28/07/2026	Gears	6
GVW	2800kg	CAP Clean	£7,025.00		

ROCK & ROLL BED, TV, ELECTRICAL SYSTEM, POPUP ROOF, GAS HOB, SINK, SIDE LOAD DOOR, AD-BLUE, E/MIRRORS, LEATHER.

Tyres

NSF

NSR

OSF



OSR

Spare

Features

- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking


Photos







Condition Check



Damage Photos



1: Fascia Panel
Broken
Replace

2: Screen Front
Chipped
Over 10mm



3: Bonnet
Dented
Over 30mm

4: Bumper Front
Cracked
Over 25mm



5: Wing osf
Dented
Over 30mm

6: Wheel osf
Dented
Over 30mm (Alloy)



7: Wheel osr
Dented
Over 30mm (Alloy)

8: Tailgate
Dented
With Paint Damage



9: Wheel nsf
Dented
Over 30mm (Alloy)



10: Door nsf
Dented
With Paint Damage

11: Wheel nsf
Dented
Over 30mm (Alloy)

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK