

# VEHICLE INSPECTION REPORT

**NU18GKG**

## Man TGX 18.420

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date 24/04/2018

Colour BLUE

Gearbox AUTOMATIC

Year 2018

VIN WMA06XZZ8JM787043

Axle Combi 4x2

Mileage 520,462 Km Warranted

Body Style Tractor Unit

Rear Suspension Air

Fuel Type DIESEL

MOT Due 31/10/2026

GVW 18000kg

Cab Type XLX CAB

### SLIDING 5TH WHEEL

### Tyres

| NSF   | NSI1 | NSI2 | NSI3 | NSI4 |
|-------|------|------|------|------|
| OSF   | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
|       | OSO1 | OSO2 | OSO3 | OSO4 |


## Features

- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim

## Photos












## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips

2: Bumper Front  
Scratched  
Over 100mm Thru Paint




3: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm

4: Door Moulding nsf  
Broken  
Replace



5: Qtr Panel nsr  
Dented  
Over 30mm

6: Door osf  
Dented  
Over 30mm



7: Qtr Panel osr  
Dented  
Over 30mm

8: Seat Base Cover osf  
Torn  
Over 3mm

## Interior

|                         |      |                             |    |
|-------------------------|------|-----------------------------|----|
| <b>Carpet Condition</b> | OK   | <b>Upholstery Condition</b> | OK |
| <b>Seat Condition</b>   | Poor | <b>Odour</b>                | -  |
| Engine Runs             | OK   | No Excessive Smoking        | OK |
| EML light illuminated   | OK   | DPF light illuminated       | OK |
| ABS light illuminated   | OK   |                             |    |