

VEHICLE INSPECTION REPORT

NU18HTF

Man TGX 18.420

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	24/04/2018	Colour	BLUE	Gearbox	AUTOMATIC
Year	2018	VIN	WMA06XZZ6JM787218	Axle Combi	4x2
Mileage	655,512 Km Warranted	Body Style	Tractor Unit	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	31/10/2026		
GVW	28000kg	Cab Type	XLX CAB		

SLIDING 5TH WHEEL

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
 Scratched
 Over 100mm Thru Paint

4: Qtr Panel Trim os
 Broken
 Replace



5: Door Pad osf
 Broken
 Replace

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		