

VEHICLE INSPECTION REPORT

BK14AOM

IVECO EUROCARGO 75E16

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 10/03/2014

Colour RED

Cab Type DAY CAB

Year 2014

VIN ZCFA675B202623252

Gearbox MANUAL

Mileage 476,655 Km Warranted

Body Style Box Van

Axle Combi 4x2

Fuel Type DIESEL

Service history Yes

Tail Lift Cantilever

GVW 7500kg

MOT Due 31/05/2027

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4


OSO1




OSO2

OSO3


OSO4

Photos






Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint

2: Bonnet
Cracked
Replace



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Chipped
Edge Chip

6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Bumper Rear
Rusted
Over 5mm

8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Door osf
Scratched
UpTo 25mm Thru Paint

10: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



11: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

12: Switches And Controls
Broken
Replace



13: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	