

VEHICLE INSPECTION REPORT

PE63NKS

Daf LF 45.140

Non Runner
Inspection

Serious Damage?	No	Vehicle	
		VAT	Plus VAT
		V5	Present

Details

Reg. date	19/11/2013	VIN	XLRAE45FF0L432777	Gearbox	MANUAL
Year	2013	Body Style	Box Van	Axle Combi	4x2
Mileage	1,093,432 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	DIESEL	Service documents	Printout	Tail Lift	Cantilever
GVW	7500kg	MOT Due	31/05/2027		
Colour	RED	Cab Type	DAY CAB		

NON-RUNNER - NO CLUTCH, WARNING LIGHTS ON DASH


Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Door nsf
Dented
Over 30mm



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

8: Door osf
Dented
Over 30mm



9: Door osf
 Scratched
 Over 25mm Thru Paint

10: Door Pad osf
 Soiled
 Heavy



11: Dash Warning Lights
 Displayed
 No Action

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
		Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	Fault		