

VEHICLE INSPECTION REPORT

PE65VDC

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 29/10/2015

Colour RED

Cab Type DAY CAB

Year 2015

VIN XLRAEL1500L448523

Gearbox MANUAL

Mileage 977,258 Km Warranted

Body Style Box Van

Axle Combi 4x2

Fuel Type DIESEL

Service history Yes

Rear Suspension Steel

GVW 7500kg

MOT Due 31/08/2026

Tail Lift Cantilever

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1


OSO2

OSO3


OSO4

Photos






Condition Check



Damage Photos



1: Wing of
Scratched
Up To 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips




3: Bumper Front
Chipped
Multiple Chips



4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

8: Bumper Rear
Rusted
Over 5mm



9: Qtr Panel osr
 Scratched
 Over 25mm Not Thru Paint

10: Door osf
 Scratched
 Over 25mm Thru Paint



11: Door Mirror Assy osf
 Broken
 Replace

12: Wing Front Arch Extension os
 Scuffed (Unpainted)
 Over 100mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK