

VEHICLE INSPECTION REPORT

EF720TK

FORD TRANSIT 290 2.0 ECOBLUE LEADER 105PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 30/11/2022

Year 2022

Mileage 44,073 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0EXXTTRENS68090

Body Style Panel Van L2

MOT Due 29/11/2025

CAP Clean £13,550.00

CAP Average £12,550.00

CAP Below £10,800.00

Gearbox MANUAL

Gears 6

WARNING LIGHTS ON DASH, FOOT BRAKE ISSUES

Tyres

NSF

NSR

OSF

OSR

Spare


Features

- Front parking sensor
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows


Photos



Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Door Mirror Assy nsf
Broken
Replace



3: Door Mirror Glass ns
Broken
Replace



4: General Exterior
Soiled
Light




5: Door nsr
Dented
Over 30mm




6: Door nsr
Dented
Over 30mm



7: Door nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Door osr
Dented
With Paint Damage



11: Door osr
Dented
Over 30mm



12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: General Exterior
Soiled
Light



15: Door Mirror Glass os
Missing
Replace



16: Door Moulding osf
Missing
Replace



17: Other
N/A
N/A

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK