

VEHICLE INSPECTION REPORT

PE65VDY

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	Colour	RED	Gearbox	MANUAL
Reg. date	29/10/2015	VIN	XLRAEL1500L448595	Axle Combi	4x2
Year	2015	Body Style	Box Van	Rear Suspension	Steel
Mileage	395,674 Km Warranted	Service history	Yes	Tail Lift	Cantilever
Fuel Type	DIESEL	Service documents	Printout		
GVW	7500kg	Cab Type	DAY CAB		

Tyres






NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Panel Front
Scratched
Over 25mm Thru Paint



3: Bumper Front
Dented
With Paint Damage

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Badgedecal Front
Missing
Replace

6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Door osf
 Scratched
 Over 25mm Thru Paint

10: Door Pad osf
 Soiled
 Heavy



11: Carpets Front
 Torn
 Over 10mm

12: Seat Base Cover nsf
 Holed
 Over 3mm

Interior

Carpet Condition		Poor	Upholstery Condition		Poor
Seat Condition		Poor	Odour		-
Engine Runs	OK		No Excessive Smoking	OK	
EML light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK				