

VEHICLE INSPECTION REPORT

HS71DFD

Ford Transit Custom 320 2.0 EcoBlue 130PS Limited

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	16/02/2022	Colour	GREY	CAP Average	£11,450.00
Year	2022	VIN	WF0ZXXTTGZME85241	CAP Below	£9,625.00
Mileage	87,167 Miles Not Warranted	Body Style	Crew Van L2	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	29/03/2027	Gears	6
GVW	3200kg	CAP Clean	£12,600.00		

TWIN SIDE LOAD DOOR, E/MIRRORS, LEATHER, HEATED WINDSCREEN, AD-BLUE.

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Front parking sensor
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm

2: Bumper Front
Cracked
Over 25mm



3: Wheel osf
Dented
Over 30mm (Alloy)

4: Sill Panel Trim os
Broken
Replace



5: Tailgate
Dented
Over 30mm

6: Wheel osr
Dented
Over 30mm (Alloy)



7: Door nsr
Scratched
Over 25mm Not Thru Paint

8: Wheel nsr
Dented
Over 30mm (Alloy)



9: Wheel nsr
 Damaged
 Replace

10: Fuel Flap
 Missing
 Replace



11: Wheel nsf
 Dented
 Over 30mm (Alloy)

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK