

VEHICLE INSPECTION REPORT

BU75NXT

Daf XB 260

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Location Doncaster

Reg. date 08/09/2025

Year 2025

Mileage 35,688 Km Not Warranted

Fuel Type DIESEL

GVW 18000kg

Colour WHITE

VIN XLRAEL3700L543874

Body Style Curtainside

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Steel

Rear Doors Barn

Tail Lift Tuckaway

WARNING LIGHTS ON DASH

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3




OSO4

Features

- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim
- Air conditioning


Photos







Condition Check



Damage Photos



1: Door Mirror Glass ns
Broken
Replace

2: Door Pad osf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK

EML light illuminated

OK

DPF light illuminated

OK

ABS light illuminated

OK