

# VEHICLE INSPECTION REPORT

**YK14CTY**

## SCANIA P 320

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | Present  |

### Details

|           |                          |            |                   |                 |                 |
|-----------|--------------------------|------------|-------------------|-----------------|-----------------|
| Reg. date | 01/05/2014               | VIN        | YS2P6X20005344512 | Axle Combi      | 6x2             |
| Year      | 2014                     | Body Style | Dropside & Crane  | Steering Combi  | Rear-Lift Steer |
| Mileage   | 248,764 Km Not Warranted | MOT Due    | 31/10/2025        | Rear Suspension | Air             |
| Fuel Type | Diesel                   | Cab Type   | DAY CAB           |                 |                 |
| Colour    | WHITE                    | Gearbox    | MANUAL            |                 |                 |

\*CRANE INOP\* FASSI F155 CRANE (YEAR 2014)

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Park assist camera
- Air conditioning

## Photos





