

VEHICLE INSPECTION REPORT

CK12EKU

Mercedes-Benz Vito 110 CDI

Non Runner
Inspection

Serious Damage?		Vehicle	
No		VAT	Plus VAT
		V5	Present

Details

Reg. date	11/04/2012	Colour	WHITE	CAP Average	£1,025.00
Year	2012	VIN	WDF63960123677792	CAP Below	£670.00
Mileage	Not Showing	Body Style	Panel Van SWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	Expired	Gears	6
GVW	2800kg	CAP Clean	£1,275.00		

NON-RUNNER-UNABLE TO RELEASE STEERING LOCK MOT SHOWS 200,721 MILES 11/10/2023, TWIN SIDE LOAD DOORS

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Rusted
Over 5mm

2: Wing nsf
Rusted
UpTo 5mm

No Image



3: A Post ns
Rusted
Over 5mm



4: Door nsf
Rusted
Over 5mm



5: Qtr Panel osr
Rusted
Over 5mm



6: Qtr Panel osr
Rusted
Over 5mm

7: Seat Base Cover osf
Holed
UpTo 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	Fault		