

VEHICLE INSPECTION REPORT

CX20WVO

Ford Ranger WILDTRAK 2.0 ECOBLUE 213PS

Non Runner
Inspection

Serious Damage?		Vehicle	
No		VAT	Plus VAT
		V5	To Follow

Details

Location	Bedford	Colour	WHITE	CAP Below	£6,750.00
Reg. date	11/06/2020	VIN	6FPPXXMJ2PLR83113	Gearbox	AUTOMATIC
Year	2020	Body Style	Pickup Double Cab	Gears	1
Mileage	Not Showing	MOT Due	Expired	Axle Combi	4x4
Fuel Type	DIESEL	CAP Clean	£9,650.00		
GVW	3270kg	CAP Average	£8,450.00		

NON RUNNER-DOES NOT POWER UP, ENGINE PARTIALLY STRIPPED AD BLUE, TOW BAR, MOT SHOWS 90,234 MILES 04/08/2025

Tyres

NSF
NSR
OSF
OSR
Spare

Features


- Rear parking sensor
- Air conditioning
- Front electric windows
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Qtr Panel nsr
Dented
Over 30mm

2: Qtr Panel osr
Dented
Over 30mm

Interior

Carpet Condition Poor
Seat Condition Average

Upholstery Condition Average
Odour -

Engine Runs	Fault	Gearbox 1st and Reverse Test	Fault
Brakes	Fault	Clutch Slip Test from Static	Fault
Turbo Boosting	Fault	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	Fault	No Excessive Smoking	Fault
EML light illuminated	Fault	Oil warning light illuminated	Fault
Airbag light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	Fault	Service indicator light illuminated	Fault