

VEHICLE INSPECTION REPORT

YK17LKY

MERCEDES-BENZ ACTROS 1827

Inspection

Vehicle

VAT	Plus VAT
V5	Buyer To Apply

Details

Reg. date	07/03/2017	Colour	BLUE	Gearbox	AUTOMATIC
Year	2017	VIN	WDB96300320119508	Axle Combi	4x2
Mileage	576,418 Km Not Warranted	Body Style	Recovery	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	31/07/2026		
GVW	18000kg	Cab Type	SLEEPER CAB		

WARNING LIGHTS ON DASH, WINCH

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Park assist camera
- Air conditioning