

VEHICLE INSPECTION REPORT

WU16PDK

DAF LF 180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Doncaster

Fuel Type DIESEL

Body Style Refuse Collector

Reg. date 01/07/2016

GVW 12000kg

MOT Due 31/12/2026

Year 2016

Colour WHITE

Mileage 162,597 Km Warranted

VIN XLRAEL1500L452639

WARNING LIGHTS ON DASH ROMAQUIP BODY

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3




OSO4

Features

- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning


Photos








Condition Check



Damage Photos



1: Door osf
Dented
With Paint Damage

2: Wing osf
Scratched
Over 25mm Thru Paint



3: Bumper Front
Dented
With Paint Damage

4: Panel Front
Scratched
Over 25mm Thru Paint



5: Bonnet
Chipped
Multiple Chips

6: Bumper Front
Dented
With Paint Damage



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

8: Door Moulding nsf
Broken
Replace



9: Door nsf
Chipped
Multiple Chips

10: Door Pad osf
Soiled
Heavy



11: Seat Base Cover osf
Torn
Over 3mm

12: Seat Base Cover nsf
Torn
Over 3mm



13: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		