

VEHICLE INSPECTION REPORT

YF66LVR

Ford Transit Connect 240 1.5 TDCI 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 20/02/2017

Year 2017

Mileage 80,079 Miles
Warranted

Fuel Type DIESEL

GVW 2395kg

Colour WHITE

VIN WF0SXXWPGSGY82714

Body Style Panel Van L2

MOT Due 17/10/2026

CAP Clean £3,325.00

CAP Average £2,750.00

CAP Below £2,050.00

Gearbox MANUAL

Gears 5

OUTSTANDING RECALL SIDE LOAD DOOR

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Front parking sensor
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wings
Dented
With Paint Damage



3: Door nsf
Dented
Over 30% Of Panel

4: Qtr Panel nsr
Dented
With Paint Damage



5: Qtr Panel nsr
Dented
With Paint Damage

6: Door osf
Dented
Over 30% Of Panel



7: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		