

VEHICLE INSPECTION REPORT

BL15YBX

Iveco Daily 70-170

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	22/06/2015	Colour	WHITE	Cab Type	DAY CAB
Year	2015	VIN	ZCFC270C805012192	Gearbox	MANUAL
Mileage	102,395 Km Warranted	Body Style	Panel Van	Axle Combi	4x2
Fuel Type	DIESEL	Service history	Yes	Rear Suspension	Steel
GVW	7000kg	Service documents	Printout		

PTO, MICROWAVE, WATER HEATER, HOIST CABLE FEEDER, 240V SOCKETS


Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Digital radio
- Passenger airbag
- Radio/CD
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front Moulding
Missing
Replace



3: Panel Front
Scratched
Over 25mm Thru Paint

4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Door nsf
Scratched
Over 25mm Thru Paint

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

10: Door osr
Dented
With Paint Damage



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint

12: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



13: Panel Front
Cracked
Replace

14: Carpets Front
Holed
Over 3mm



15: Seat Base Cover osf
Holed
Over 3mm

16: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition		Poor	Upholstery Condition		Poor
Seat Condition		Poor	Odour		-
Engine Runs	OK		No Excessive Smoking	OK	
EML light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK				