

VEHICLE INSPECTION REPORT

BT15KYS

Iveco Daily 70-170

Inspection

Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details

Location	Doncaster	GVW	7000kg	Service documents	Printout
Reg. date	08/06/2015	Colour	WHITE	Cab Type	DAY CAB
Year	2015	VIN	ZCFC270C205011054	Gearbox	MANUAL
Mileage	177,302 Km Warranted	Body Style	Panel Van	Axle Combi	4x2
Fuel Type	DIESEL	Service history	Yes	Rear Suspension	Steel

PTO, MICROWAVE, WATER HEATER, 240V SOCKETS, HOIST, CABLE FEEDER


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Digital radio
- Passenger airbag
- Radio/CD
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Bumper Front Moulding
Missing
Replace

4: Wing nsf
Dented
Over 30mm



5: Qtr Panel nsr
Dented
Over 30mm

6: Qtr Panel nsr
Dented
Over 30mm



7: Qtr Panel nsr
Dented
Over 30mm

8: Door nsr
Dented
Over 30mm



9: Door osr
Dented
With Paint Damage

10: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



11: Seat Base Cover osf
Holed
Over 3mm

12: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		