

VEHICLE INSPECTION REPORT

BV65YKS

Iveco Daily 70-170

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	15/09/2015	Colour	WHITE	Cab Type	DAY CAB
Year	2015	VIN	ZCFC270CX05039748	Gearbox	MANUAL
Mileage	104,079 Km Warranted	Body Style	Panel Van	Axle Combi	4x2
Fuel Type	DIESEL	Service history	Yes	Rear Suspension	Steel
GVW	7000kg	Service documents	Printout		

PTO, RACKING IN REAR, MICROWAVE, WATER HEATER, CABLE FEEDER, HOIST

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Digital radio
- Passenger airbag
- Radio/CD
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Qtr Panel nsr
Dented
With Paint Damage



3: Door osr
Dented
Over 30mm

4: Door osr
Dented
With Paint Damage



5: C Post os
Dented
With Paint Damage

6: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

8: Qtr Panel osr
Dented
Over 30mm



9: Carpets Front
Torn
Over 10mm

10: Seat Base Cover osf
Soiled
Heavy



11: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		