

VEHICLE INSPECTION REPORT

BC15AKO

Iveco Daily 70-170

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	7000kg	Service documents	Printout
Reg. date	03/08/2015	Colour	WHITE	Cab Type	DAY CAB
Year	2015	VIN	ZCFC270C705038766	Gearbox	MANUAL
Mileage	148,200 Km Warranted	Body Style	Panel Van	Axle Combi	4x2
Fuel Type	DIESEL	Service history	Yes	Rear Suspension	Steel

PTO, MICROWAVE, WATER HEATER, 240V SOCKETS, RACKING, CABLE FEEDER

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Bluetooth connection
- Digital radio
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Roof
Dented
With Paint Damage

2: Bonnet
Dented
With Paint Damage



3: Bonnet
Chipped
Multiple Chips



4: Door nsf
Chipped
Multiple Chips




5: Qtr Panel nsr
Chipped
Multiple Chips




6: C Post ns
Dented
With Paint Damage



7: Door nsr
Dented
With Paint Damage



8: Door osr
Dented
With Paint Damage





9: Qtr Panel osr
Dented
With Paint Damage

10: Screen Front
Chipped
Over 10mm



11: Carpets Front
Holed
Over 3mm

12: Seat Base Cover osf
Torn
Over 3mm



13: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		