

VEHICLE INSPECTION REPORT

BV65YKT

Iveco Daily 70-170

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	7000kg	Service documents	Printout
Reg. date	01/10/2015	Colour	WHITE	Cab Type	DAY CAB
Year	2015	VIN	ZCFC270C305038215	Gearbox	MANUAL
Mileage	103,030 Km Warranted	Body Style	Panel Van	Axle Combi	4x2
Fuel Type	DIESEL	Service history	Yes	Rear Suspension	Steel

INTERMITTENT PTO/ GEAR FAULT - PTO ENGAGES WHILST DRIVING

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Digital radio
- Passenger airbag
- Radio/CD
- Central locking


Photos








Condition Check



Damage Photos



1: Wing osf
Dented
Over 30mm

2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Bonnet
Chipped
Multiple Chips

4: Door osf
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Qtr Panel Moulding ns
Broken
Replace



9: Door nsr
Dented
With Paint Damage

10: Door osr
Dented
With Paint Damage



11: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

12: Seat Base Cover osf
Torn
Over 3mm



13: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		