

VEHICLE INSPECTION REPORT

BT15TKZ

Iveco Daily 70-170

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Bedford

GVW 7000kg

Cab Type DAY CAB

Reg. date 08/06/2015

Colour WHITE

Gearbox MANUAL

Year 2015

VIN ZCFC270C905011505

Axle Combi 4x2

Mileage 57,341 Km Warranted

Body Style Panel Van

Rear Suspension Steel

Fuel Type DIESEL

MOT Due 30/06/2027

COMPRESSOR, RACKING

Tyres

NSF NSI1 NSI2 NSI3 NSI4



OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Photos





Condition Check



Damage Photos



1: Wing osf
Dented
With Paint Damage



2: Bonnet
Rusted
UpTo 5mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK