

VEHICLE INSPECTION REPORT

YY74NHO

Fiat Ducato 35 2.2 III MULTIJET 140PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Location Doncaster

Reg. date 18/10/2024

Year 2024

Mileage 30,290 Miles Not Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN ZFA25000002Y37018

Body Style Luton XLWB

Gearbox MANUAL

AD-BLUE, INSULATION BLOWING EQUIPMENT (PUMP REMOVED), E/ MIRRORS

Tyres

NSF

NSR

OSF


OSR



Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking


Photos







Condition Check



Damage Photos



1: Door Mirror Assy osf
Broken
Replace

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm

4: Qtr Panel osr
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		