

VEHICLE INSPECTION REPORT

YY74NHP

Fiat Ducato 35 2.2 MULTIJET III

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Location	Doncaster	Fuel Type	DIESEL	Body Style	Luton XLWB
Reg. date	18/10/2024	GVW	3500kg	Gearbox	MANUAL
Year	2024	Colour	WHITE		
Mileage	45,751 Miles TBC	VIN	ZFA25000002Y46066		

WARNING LIGHTS ON DASH AD-BLUE, INSULATION BLOWING EQUIPMENT (PUMP REMOVED), E/ MIRRORS

Tyres

NSF

NSR

OSF


OSR




Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking


Photos







Condition Check



Damage Photos



1: Door Mirror Assy osf
Broken
Replace



2: Screen Front
Cracked
Replace




3: Bonnet
Chipped
Multiple Chips

4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Door nsr
Dented
Over 30mm

6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

8: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK		